USER MANUAL



DI-300SS

EDITION 02

Table of Content

Notice	1
Safety Information	2
Specifications	
General	
Digital Section	
Analog Section	3
Interface	
Overall View of DI-300SS	
Product Layout	6
Display Panel and Key Sheet Layout	6
Indicators	6
Keys Function	7
Interface	9
Interface	
Interface	······································
Start Up And Segment Check	
Date And Time View & Setting	
Tare Operation	14
ONE TOUCH TARE	
DIGITAL TARE	16
Tare Value Exchange	
TARE ACCUMULATION	17
TARE SUBTRACTION	19
Weighing Mode	
PLU Call -Up In Weighing Mode	
PLU Call-Up In Weighing Mode	22

PLU Programming	24
General Set Point Password Setting	30
Functions Operation	32
Example of Function and Indicator Layout	
Weight Conversion	
Accumulation and Subtraction	35
1. Accumulation	35
2. Subtraction	40
Sequence Number	44
Net/Gross	46
Lot Number	47
Hold	49
1. Peak Hold	49
2. Normal Hold	50
Counting and Quantity	52
Set-Point	55
1. Set-Point Setting	55
2. Weighing Operation with Set Point	59
IP Address Setting	
Server IP Address Setting	
Error Messages Description	65
Notes	67

Notice

DIGI®

The material contained in this document is proprietary and for information only and is subject to change without notice. Teraoka Weigh-System assumes no responsibility for any errors or damages arising from misinterpretation of any procedure.

Screen displays, operating procedures and supporting features might vary with different software version releases.

This document shall not be reproduced whether in part or whole without the written consent from Teraoka Weigh-System Pte Ltd.

Teraoka Weigh-System Pte Ltd 4, Leng Kee Road #06-01 SIS Building Singapore 159088

Safety Information

The operator of the equipment shall comply with the safety and warning indications and procedures outlined in this document. Teraoka Weigh-System Pte Ltd assumes no responsibility or liability for failure to comply with these requirements.

- To avoid electric shock, use only the supplied power cords and ensure product is connected to a properly grounded supply.
- For continued protection against fire hazard replace only with fuse of same rating and type.
- Ensure product is placed on a firm and level surface before operation.
- Avoid overloading the product beyond its rated maximum capacity
- Repair and servicing of product shall only be carried out by trained and qualified personnel.

Disclaimer:

Specifications are subject to change without notice. All dimensions shown are approximate. Please be aware that Teraoka has indicated that its hardware and software used in the product may require additional updates in the future as our product is continually under development. The need for such updates most likely applies to the Printer software.

CAUTIONS:

- 1. FOR PLUGGABLE EQUIPMENT, THAT THE SOCKET-OUTLET SHALL BE INSTALLED NEAR THE EQUIPMENT AND SHALL BE EASILY ACCESSIBLE.
- 2. FOR CONTINUED PROTECTION AGAINST RISK OF FIRE, REPLACE IT ONLY WITH SAME TYPE AND RATING OF FUSE.
- 3. DANGER OF EXPLOSION IF BATTERY IS INCORRECTLY REPLACED. REPLACE ONLY WITH THE SAME OR EQUIVALENT TYPE THAT RECOMMENDED. DISPOSE OF USED BATTERY ACCORDINGS TO THE MANUFACTURER'S INSTRUCTIONS.

Specifications

General

Model : DI-300 SS

: DI-300C-SS (Bar-graph)

: DI-300D-SS (Bar-graph and LCD display)

Power Source : AC 110V - 240V (50 / 60 Hz)

Operation Temperature : - 10°C – 40°C

Humidity : 15% to 85% RH

Memory : 100 Items

Digital Section

Function Key : 24 Keys

Indicator Sign : 8 Indicators

Display Resolution : 50,000 counts

Main Display : 7 Segment 6 digit LED at 24.5mm

Analog Color bar : 8 X 3 Color = 24 LED (DI-300C-SS only)

LCD Display : Alphanumeric 16 Digits (DI-300D-SS only)

Analog Section

Zero adjustment range : 0.35mV – 24mV

Max Load Cell input voltage : 36mV

A/D Conversion Method : Delta Sigma A/D Resolution : 600,000 counts

A/D Conversion Rate : 200 times/sec (maximum)

Interface

Interface : AC Inlet

: Set Point Interface

: RS 232/RS 485 Interface

: Ethernet Interface

: Scale (load cell) Interface


*Specifications are subject to change without notice

Overall View of DI-300SS

DI-300SS





DI-300SS Schematic Drawing



Product Layout

Display Panel and Key Sheet Layout





Indicators

NET

: Light when Main Display is showing NET Weight or Tare Value is being applied to the current Gross Weight reading.

ZERO

: Light when Scale at the zero point.

MOTION

: Light when weight is unstable. Or off when the scale is stable.

SET

: Light when the scale is in Set Up Mode, when doing rezero or when

entering numeric data.

Weight Unit Weight unit indicator. (g, kg and Lb)

Light when using the assigned function in function keys, except some FNC 1, 2 & 3

function which do not light when using the function key.

Set Point Lamp Lighted when weight reach set point limit.


Weight unit indicator, used when Weight Conversion function is Weight Unit (2)

enabled

Keys Function	
NUMERIC KEYS	
o to	: Enter numeric data.
MODE KEY	
	Toggle in Programming Mode, Password Mode, Date and Time Mode and Weighing Mode.
RE-ZERO KEY	
> 0€	: Reset weight to ZERO.
CLEAR KEY	
C	: Clear numeric data, cancel and go to previous.
TARE KEY	
→T ←	: Set or Clear Tare value.
CODE KEY	
#	: Call up PLU.
DOT KEY	
	: To enter Decimal point.
ENTER KEY	
Θ	 Sending weighing data Save and exit in PLU programming, Spec mode, IP setting, Subnet setting. Password entering.

SET POINT SETTING	KEY	7.
		- Set point setting.
	:	- Decrease Spec number for selection.
FUNCTION 1 KEY		
(FNC 1)	:	To run function assigned for function 1 key (depend on spec 44)Enter key in Date and Time setting.
		- Up and down in Spec selection
FUNCTION 2 KEY		
(FNC 2)		- To run function assigned for function 2 key (depend on spec 45)
	•	- Up and Down in Spec selection.
FUNCTION 3 KEY		
(FNC 3)		- To run function assigned for function 3 key (depend on spec 46)
	•	- Increase Spec number for selection.

Interface



Interface	
1	Span Switch
2	Boot Switch
3	AC Power Inlet
4	Set Point Interface
5	RS 232/ RS 485 Interface (optional)
6	Ethernet Interface
7	Scale (Load cell) Interface

Start Up And Segment Check

OPERATION DISPLAY 1. Connect to AC plug supply and remove any item on platforms and then turn "ON" the power switch. Note: The Software Version Number will appear on the display. 2. After finish segment check, Scale on Stand -By - Status. (Picture 1) NET Note 1: If any items on the Platforms and it exceeds scale start range, following error message SET will appear, press [CLEAR] key to exit or remove the item from platforms. Also happen if Picture. 1 platform not connected (Picture 2) Picture 2

Date And Time View & Setting

Date and time is user programmable.

OPERATION	DISPLAY
1. At Stand-by-Status (Weighing Mode)	NET → 0 ← SET kg INICH INIC
2. Press [MODE] key three times to go to Date & Time view/setting mode Note: First it display Screen 1, then automatically change to Screen 2 and then automatically change to screen 3 Note: Time displayed on scale screen 3 e.g. 12:00pm (as current time)	NET $\rightarrow 0 \leftarrow$ SET Screen 1 NET $\rightarrow 0 \leftarrow$ SET Screen 2 NET $\rightarrow 0 \leftarrow$ SINCE SCREEN 2
	Ser Screen 3

OPERATION	DISPLAY
3. Press [FNC 1] key to view Current Date on scale e.g. 02.01.25 (yymmdd)	NET +0+ 020125 kg NET +0+ 020125 INC
4. Press [FNC 1] key again, it display Current Day on scale. e.g. Friday	NET → 0← SET kg NNCI NNCI
5. Press [FNC 1] key again, it display Date Format	NET SET SET SET
6. Enter a valid date by using [NUMERIC] key e.g. 050616 (yymmdd)	NET OS SET SET SET SET SET SET SET SET SET SE

OPERATION	DISPLAY
7. Press [FNC 1] key again, it display Time Format	NET + 0+ kg NET - 1
8. Enter a valid time by using [NUMERIC] key e.g. 142500 (hhmmss)	NET +0+
9. Press [FNC 1] key	NET +0+ SET
10. Enter a valid day by using [NUMERIC] key. E.g. 3, then press [ENTER] key to save and exit. No. Days 0	NET ◆ →0← ◆ SET ◆ NET

Tare Operation

There are two ways to set Tare Weight, **One Touch Tare and Digital Tare**. Usage of Tare depending on **SPEC 215 "Tare Operation"** and the limit of Tare Weight is depending on **SPEC 214 "Tare Range"** setting. The following operation examples show two ways of subtracting the Tare Weight of a 20g tray.

Note: To enable this function, set SPEC 215 to "1" or "3" in advance.

Note: SPEC 202 "Zero Lamp" is set to 1 "Net" (Zero Lamp display depend on this spec)

ONE TOUCH TARE

This function is to weight the actual weight of the tare then subtract its weight to get the tare value.

OPERATION	DISPLAY
At Stand-by-Status (Weighing Mode) Put a Weight on to the Platform e.g. 20g	NET →0← →0← SET • OOO OO OO OOO OOOO OOOOOOOOOOOOOOOO
2. Press [TARE] key	NET →0← ~ SET SET SET SET SET SET SET SET SET SET
3. Remove Weight	NET -

OPERATION	DISPLAY
4. Press [TARE] key to clear the tare weight.	NET OCCUPANT SET ROCCUPANT INTER INTE

DIGITAL TARE

This function can be used when tare weight is decided/known in advance. Tare subtraction can be performed by enter numeric value. Usage of Tare depending on **SPEC 215 "Tare Operation"** and Digital Tare Rounding method is depending on **SPEC 217 "Digital Tare Rounding"** setting.

Note: To enable this function, set SPEC 215 to "2" or "3" in advance.

Note: SPEC 202 "Zero Lamp" is set to 1 "Net" (Zero Lamp display depend on this spec)

OPERATION	DISPLAY
At Stand-by-Status (Weighing Mode), enter the tare weight by [NUMERIC] key (e.g. 20g)	NET OCCUPANT SET INTER I
2. Press [TARE] key to subtract the tare weight.	NET -
3. Press [TARE] key to clear the tare weight.	NET → 0←

Tare Value Exchange


There are two ways to do tare value exchange, **Tare Accumulation** and **Tare Subtraction**. One Touch Tare and Digital Tare can be used to do Tare Accumulation or Tare Subtraction.

Note: To use both One Touch Tare and Digital Tare function at same time must enable SPEC 218 "Digital Tare When Loaded"

TARE ACCUMULATION

To enable this function, SPEC 216 "Tare Exchange" and SPEC 219 "Tare Increase", must be set to 1 "Yes" in advance.


OPERATION	DISPLAY
 Stand-by-Status (Weighing Mode) Put a Weight on to the Platform e.g. 20g Note: Also can use digital tare. 	NET OCCUPANTE SET ROCCU INVENT
2. Press [TARE] key to subtract the tare weight	NET +0+
3. Place another tare weight on the platform (Ex. 50g). Note: Also can use digital tare. Note: For Digital Tare, the next tare accumulation value should not be lower than the previous tare value.	NET +0+ -0+ SET



TARE SUBTRACTION

To enable this function, SPEC 216 "Tare Exchange" and SPEC 220 "Tare Decrease", must be set to 1 "Yes" in advance.

OPERATION	DISPLAY
 Stand-by-Status (Weighing Mode) Put a Weight on to the Platform e.g. 100g and Press [TARE] key to subtract the tare weight Note: Also can use digital tare. 	NET →0← SET
Remove 20g from the platform Note: For Digital Tare, subtracted tare value should not be bigger than the total tare value.	NET •
3. Press [TARE] to subtract the weight.	NET →0←



Weighing Mode


It works by weighing any weight/item on the platform and the display will show the weighing data. It is **not** required to program any plu in advance.

OPERATION	DISPLAY
1. At Stand-by-Status (Weighing Mode)	NET O CO
2. Put a Weight on to the Platform e.g. 1Kg	NET →0← SET
3. Press [ENTER] key to send out the weighing data. Note: [ENTER] key used to send data to ID Manager, PC or etc. Note: When connect to some application, it might show other screen before this screen, For e.g. ID MANAGER, when press [ENTER] key, it display SENT first, then show the value screen and later show ACK (acknowledged)	NET →0← SET

PLU Call -Up In Weighing Mode

To call up PLU in weighing mode, the plu must be programmed in advance. PLU can be called up from application like 'ID MANAGER' or database within the scale. The selection of plu source depends on the SPEC 51 'PLU Source'. Please refer to PLU Programming to program plu data.

Note: SPEC 402 "Weight Checking type" currently set to 0 "Sequence weight check".




OPERATION	DISPLAY
4. Load desired weight e.g. 2kg	NET →0← →0← SET
 5. Press [ENTER] key to send out the weighing data. Note: [ENTER] key used to send data to ID Manager, PC or etc. Note: When connect to some application, it might show other screen before this screen, For e.g. ID MANAGER, when press [ENTER] key, it display SENT first, then show the value screen and later show ACK (acknowledged) 	NET →0← →


PLU Programming


To program plu data within the scale database.

OPERATION	DISPLAY
At Stand-by-Status (Weighing Mode), Press [MODE] key once to enter PLU Programming mode.	NET DI DE ROCCE SET DI DE ROCCE INICE INIC
Enter new PLU number e.g. 123 by pressing [NUMERIC] key	NET OCT SET kg HINGS INCOMES
3. Press [CODE] key	NET OCCUPATION SET INTERIOR INTERIOR INTERIOR INTERIOR INTERIOR INTERIOR INTERIOR INTERIOR INTERIOR INTERIOR INTERIOR INTERIOR INTERIOR

OPERATION	DISPLAY
4. Enter Tare value ex. 0.100, and press [TARE] key	NET OF SET NET Kg INVEN INV
5. Press [FNC 1] key to set set-point value Note: Screen non-stop switching between screen 1 and 2	NET O SET Screen 1 NET Screen 2
6. Enter correct password by using [NUMERIC] key e.g. 112 Note: To program password, please refer to General Set Point password setting	NET → 0← SET kg HINGE MINIST







	OPERATION	DISPLAY
16.	Press [FNC 3] key to save and return to PLU file programming main screen Note: Press [C] key to exit without saving	NET OF SET NET ROCK NOTE NOT
17.	Press [ENTER] key to save programmed plu file Note: Press [Mode] or [C] key to exit without saving	NET DE DE ROCK NET DE DE ROCK NET DE ROCK
18.	Press [MODE] key 3 times to return to Stand-by-Status (Weighing Mode)	NET →0← SET

General Set Point Password Setting

General Set Point password setting is used for general set point protection.

OPERATION	DISPLAY
 At Stand-by-Status (Weighing Mode), Press [MODE] key two times to enter password mode. Note: The first screen displayed few second and then automatically goes to Screen 2. 	NET →0← SET NET → Kg ←FNC1 ←FNC2 ←FNC3 Kg ←FNC3 FNC3 Screen 2
2. Enter old password by using [NUMERIC] key e.g. 111 (max up to 6 digit) and then press [ENTER] key,	NET →0← FNC 1 FNC 2 SET FNC 3
If wrong password entered, it display error message	NET

OPERATION	DISPLAY
4. If correct password entered it goes to next screen.	NET →0← →0← → □ □ □ □ □ FNC1 → FNC2 → FNC3
5. Enter new password by using [NUMERIC] key e.g. 112	NET →0←
6. Press [ENTER] key to save the password. And then press [MODE] key 2 times to return to stand-by-status mode.	NET →0←

Note: If you forget your password, please contact your distributor for assistant.

Functions Operation


Different type of function available for selection, and the indicator set on scale depend on the function selected. Only can select three different functions (FNC 1, FNC 2 and FNC 3).


Function selection depend on SPEC 44 'Function 1 Keys Mode,

SPEC 45 'Function 2 Keys Mode,

SPEC 46 'Function 3 Keys Mode,

Example of Function and Indicator Layout







FNC 1 Weight Conversion

FNC 2 N/AFNC 3 N/A FNC 1 Accumulation FNC 2 Subtraction

FNC 3 Sequence Number

- * For subtraction used the same indicator as Accumulation
- * For Sequence Number no functions indicator is used





FNC 1 Gross FNC 2

Lot Number

FNC 3 Hold FNC₁ Counting (sample)

FNC 2 Quantity FNC 3 Set Point

* Quantity is used to display current quantity for sampling weight and no indicator is used for quantity

* For set point no functions indicator is used

^{*} When use weight conversion, FNC 2 and FNC 3 cannot be used

Weight Conversion

Weight conversion used for converting of current weight unit to other weight unit with the same weight used.

Note: when select weight conversion, other function cannot be set, FNC 2 and FNC 3 key will be disabled

OPERATION	DISPLAY
1. At Stand-by-Status (Weighing Mode), Load Weight e.g 1kg	NET • • • • • • • • • • • • • • • • • • •
2. Press [WEIGHT CONVERSION] function key (1 times) to view weight in gram	NET
3. Press [WEIGHT CONVERSION] function key (2 times) to view weight in pound (lb)	NET


OPERATION	DISPLAY
4. Press [WEIGHT CONVERSION] function key (3 times) to view weight in ounce (oz)	NET
5. Press [WEIGHT CONVERSION] function key (4 times) to view back, weight in kg (original weight unit)	NET

Accumulation and Subtraction

Accumulation and subtraction is used for calculation of weight/item.


1. Accumulation

OPERATION	DISPLAY
1. At Stand-by-Status (Weighing Mode),	NET → 0←
2. Call up PLU e.g. 123 by using [NUMERIC] key and [CODE] key	NET OCT SET Kg ACC. RUGGE Company ACC. RUGGE Company
3. Put a weight on to the platform e.g. 300g	NET OC SET Reg ACC.





OPERATION	DISPLAY
7. Put a weight on to the platform e.g. 500g	NET →
8. Press [ACCUMULATION] function key to add item to accumulation mode Note: When press accumulation key it display Screen 1, then automatically change Screen in sequence until Screen 3 Note: Screen 2 displays the total value of accumulated item weight. Note: When connect to some application, it might show extra screen	Screen 1 NET Screen 1 NET Screen 2 NET Screen 2 NET Screen 3
9. Press [C] key to clear PLU and remove weight from platform	NET →0← SET kg ACC. ACC. Magenta ACC. Magenta


	OPERATION	DISPLAY
10.	Put a weight on to the platform e.g. 350g (Non-PLU)	NET →
11.	Press [ACCUMULATION] function key to add weight to accumulation mode Note: When press accumulation key it display Screen 1, then automatically change Screen in sequence until Screen 3 Note: Screen 2 displays the total value of accumulated item weight. Note: When connect to some application, it might show extra screen	NET →0 ← ACC. SET Screen 1 NET →0 ← ACC. SET Screen 2 NET →0 ← ACC. SET Screen 3
12.	Press [ENTER] key to send out the weighing data and exit Accumulation Mode Note: When press accumulation key it display Screen 1, then automatically change Screen in sequence until Screen 3 Note: Screen 2 displays the total value of accumulated item weight. Note: When connect to some application, it might show extra screen	NET -04




2. Subtraction










Sequence Number

Sequence number function key used to view current sequence number and modifies current number value. Sequence number only operational during printing (each time do printing, sequence number increased by 1). Max sequence number is 999999, once reach it, it will reset the number back to 0.

Note: Set Spec 52 "Output Type", to 2 "Label Printer", in advance.



OPERATION	DISPLAY
 Press [SEQUENCE NUMBER] function key to save the sequence number value Note: When print it increase the sequence number value Note: Press [C] key to clear entered data 	NET → 0← ACC. SET • INC.


Net/Gross

Gross function is used to display total weight (tare weight + net weight) of item on platform.

OPERATION	DISPLAY
 At Stand-by-Status (Weighing Mode), Assign a tare (digital tare) value e.g. 50g Note: If do one touch tare, it display as zero. 	NET -
2. Put a Weight on to the Platform e.g. 300g	NET • kg Gross Lot # Hold
3. Press [NET/GROSS] function key to view gross weight (tare weight + net weight)	NET →0 ←
4. Press [NET/GROSS] function key again to exit gross mode and view back net weight	NET • kg • Gross • Lot # Hold

Lot Number

Lot number function key used to view and temporarily modifies PLU lot number. Also used to program lot number for weighing mode (non-Plu). Max number of data allowed for entry is 20 digits.



OPERATION	DISPLAY
 4. Press [LOT NUMBER] function key to save the lot number value Note: For Plu only temporarily save, when recall the plu, it display the original plu lot number Note: Press [C] key to clear entered data 	NET • kg • Gross • Lot # Hold

Hold

Hold function is used to hold/capture weight for unstable weigh (e.g. when weighing animal and etc), also used to view weight (e.g. for recording data purpose and etc). There is two type of hold function (peak hold and normal hold), selection depend on the **SPEC 50 Hold Method**

Note: Must set SPEC 50 Hold Function to 1:Enable in advance

1. Peak Hold

Peak hold function work by detecting the peak/highest weight reached when item placed on platform

OPERATION	DISPLAY
1. At Stand-by-Status (Weighing Mode)	NET →0←
Press [HOLD] function key to enable holding function	NET • kg • Gross • Lot # Hold
3. Press the platform and release it. e.g. the weight reach 1.736 kg	NET • kg Gross Lot # Hold

OPERATION	DISPLAY
 The hold function hold the pick weight e.g. 1.736 kg Note: If when do pressing platform and release with a weight on platform the zero lamps will be off. 	NET OF O
 Display return to normal after few seconds. (The hold weight and lamp cleared) Note: If a weight is on platform, it display the weight value 	NET →0←

2. Normal Hold

Normal hold function work by detecting the stable weight when item placed on platform


OPERATION	DISPLAY
1. At Stand-by-Status (Weighing Mode)	NET • kg • Gross • Lot # • Hold

OPERATION	DISPLAY
Press [HOLD] function key to enable holding function	NET →0← SET kg Gross Lot # Hold
3. Put a weight on platform e.g. 2 kg	NET • • • • • • • • • • • • • • • • • • •
 After weight stabled, remove the weight Note: Hold function work only when the weight is stable. 	NET O CONTROL Reg Gross Lot # Hold
5. Display return to normal after few seconds. (The hold weight and lamp cleared)	NET O CONTROL Reg Grosss Lot # Hold

Counting and Quantity

Counting is used to create simple mode of counting/sampling of unit weight for item. Quantity is used to view current quantity of weight (when unit weight is available).

OPERATION	DISPLAY
1. At Stand-by-Status (Weighing Mode), Load Weight e.g. 200 g	NET OCCUPANT ROSET NET ROSET RO
2. Enter known quantity number for 0.200g e.g. 10 pcs using the [NUMERIC] key	NET → 0← → 0← SET kg Pcs Publication NET
3. Press [COUNTING] function key to do count sample weight Note: When do counting, it do computation as "weight/pcs", so 0.200g/10 pcs = 0.020g/per pcs (unit weight)	NET →0← →0← SET





OPERATION	DISPLAY
7. Remove (all) Weight and press [C] key to clear/exit counting function	NET → 0←


Set-Point


General Set Point setting is used to program or change weight Set Point data (Non-PLU item) which to be used in Stand-By-Status Mode.


1. Set-Point Setting











2. Weighing Operation with Set Point

It works by weighing the weight/item on the platform and set point used to indicate reaching of target/requested weight, where the set point lamp (or with buzzer) will be activated.


Note: To enable Weighing Operation with Set Point, SPEC 240 "Weight Checking" set to 1 "Yes".

Note: There is Internal (On Scale) and External Set Point Lamp (Connect to Set Point interface).

Note: For Internal Set Point Lamp when weight above set point 3 value, the last led lamp will blink.

Note: External Set Point Lamp display, depend on SPEC 235 "Set Point Latch", currently set to 1 "YES".


Note: SPEC 402 "Weight Checking type" currently set to 0 "Sequence weight check".



OPERATION	DISPLAY
 2. Put a Weight on to the Platform e.g. 500g Note: Internal and External Set Point 1 lamp is ON Note: Press [ENTER] key to send out the weighing data. 	NET +0+
 Add another 500g on the Platform. (Equal to 1 kg) Note: Internal Set Point 2 lamp is ON and External Set Point 1 & 2 lamp is ON Note: Press [ENTER] key to send out the weighing data. 	NET O C SET ROCK NOTE
 4. Add another 500g on the Platform. (Equal to 1.5 kg) Note: Internal Set Point 3 lamp is ON and External Set Point 1, 2 & 3 lamp is ON Note: Press [ENTER] key to send out the weighing data. Note: Internal set point lamp only support for 3 set point 	NET OF SET
5. Remove all the Weight from Platform	NET →0← SET kg Pcs INNE INN

IP Address Setting

DI 300 SS features with TCP/IP network connection. IP set up is described as follow: e.g. 192.168.0.1 (get a valid IP from your IT Administrator)




OPERATION	DISPLAY
4. Press [ENTER] key, Then enter 2 nd byte of the IP e.g.168	NET +04
5. Press [ENTER] key, Then enter 3 rd byte of the IP e.g. 0	NET OC SET Market Mark
6. Press [ENTER] key, Then enter the 4 th byte of the IP e.g. 1	NET OC SET kg MINICE INCE IN
7. Press [ENTER] key to save and exit	NET +04 PROCESSET SET

Server IP Address Setting

Other than IP setting, Server IP set up is described as follow: e.g. 192.168.0.2

OPERATION	DISPLAY
1. At Stand-by-Status (Weighing Mode)	NET →0← SET
Press 0417 (use [NUMERIC] key) while pressing [REZERO] key.	NET →0← SET kg INCO
3. Enter 1 st byte of the Server IP e.g.192	NET +0+ 5 1 1 2 kg INCO



Error Messages Description

Error message	Error description	
ID Mgr Communication Error		
ERRC 1	Ethernet no connection	
ERRC 2	Send error	
ERRC 3	Receive timeout	
ERRC 4	Receive error	
ERRC 5	Database write error	
ERRC 6	Database memory error	
ERRC 7	Ethernet board error	
Weight Measure Error		
ERR 1	Calibration error	
ERR 2	Calibration map error, not follow the setting table	
ERR 3	data entered is great than capacity	
ERR 4	AD error	
ERR 5	Can't enter float data or no data entered	
ERR 6	Keying in resolution map error	
ERR 7	Set RTC error. E.g.set month>12	
ERR 8	Set point configure error/ data enter > capacity/ sp[i+1]<=sp[i]	
ERR 9	Decimal is 0. Maybe memory corrupt	
ERR 10	Gross < Zero raw, tare operation error, clear tare if tare on	
ERR 11	When one touch only, can't enter data except 0	
ERR 12	When digit tare only, can't enter "TARE" except clear tare	
ERR 13	Digital tare when loaded can't fulfill	
ERR 14	Enter data or weight is great than tare range	
ERR 15	Weight not stable when tare or rezero operation need stable. Spec 11 set to 0	
ERR 16	Spec setting is tare can't increase or decrease	

ERR 17	tare condition error
ERR 18	Neg weight send to ID Mgr error
ERR 19	ID Client send stable timeout
ERR 20	Wait for stable timeout error
ERR 21	Haven't get dry weight (for Vietnam request)
ERR 22	Can't change set point value when not in first unit
ERR 23	Accumulation error
ERR 24	Digit numbers after decimal point greater than No of decimal setting when do tare operation
ERR 25	Error scan barcode

Notes